MAINTENANCE Guide



November 2016

NOTA BENE: The Omnisports products are factory treated with the innovative Topclean X-trem performance (XPTM).

Topclean XPTM is a UV-reticulated polyurethane treatment, which offers an excellent resistance to wear and tear.

Please note that to provide the end-customer with the best use of the flooring, the maintenance procedure must carefully be followed. If not, Tarkett Sports will decline all potential damages following a non appropriate maintenance procedure.

GENERAL ADVICES

- The players must wear appropriate shoes with white soles dedicated to Indoor Sports practise.
- It is strongly recommended to install a doormats at the entrance of the gymnasium.
- Tarkett recommends Emco mats.
- These mats can be built up with different materials, that help to catch humidity, dirt, dust....:

A griddy part, that allows to remove gravels, ground particles..., A synthetic part to catch dust under soles,

A textile part dedicated to absorption of humidity.

Emco France SAS - 8 rue des perrières Z.I.- 39700 Dampierre Tel: +333 84 80 16 20/Fax: +333 84 80 16 21/E-mail: info@emco.fr

DAILY MANUAL CLEANING

Consists in removing dust and gravels by sweeping or vacuum cleaning.

PERIODICAL CARE

- Machine cleaning: use an automatic scrubber machine fitted out with white soft brushes or white pads.
- Recommend autoscrubber: Rotowash B60 manufactured by Rotowash Company.
- A floor-cleaner(pH7 to 9) is convenient (dilution 1%), our advice:

Tanex Trophy – Tana Professional : 3 Avenue du Canada - 91940 Les Ulis Tél : +331 69 18 95 30 / Fax : +331 69 28 23 54 / Email : professionalfrance@werner-mertz.com

Jontec Asset – Johnson Diversey - johnsondiversey.com

Rotowash France: 41 rue du Mûrier - Equatop - 37540 St Cyr sur Loire

Tél: 02 47 41 11 10 / Fax: 02 47 41 00 15

Important: Please follow manufacturer's recommendations.

PERIODICAL CARE OR REFRESHMENT OF THE SURFACE

A periodical care can be done by using a cleaning machine like Rotowash B60 fitted out with nylon brushes or red pad, a floor cleaner (Tanex Trophy) with a 10% dilution is recommended. Apply the mix (water/Tanex Trophy) without vacuuming – Let the product soak into the floor for 5 minutes and then vacuum the surface.

Important: Please follow manufacturer's recommendations.

STAINS REMOVAL

- Spills should be wiped up quickly, by using a white clean cloth, before they have time to set, then clean the floor with clear water.
- For stubborn stains on the floor (handball players resin for instance), on goal posts, on seats.... Spray Tanex Trophy dilution 20%, let it work during 1 minute and sweep with a white clean cloth.

Important: Please follow manufacturer's recommendations.

NON SPORTIVE EVENTS


- When organising non sportive activities (exhibitions, concerts...) in sporthall, it is required to protect the sport flooring.
- Tarkett Sports proposes a wide range of protection covering, such as: ProtecTiles
 Touchdown
- For any further information please contact our Sales representatives or your regular Tarkett dealer.

The information given in this technical specification is indicative. It is based on our knowledge and experience. It has to be considered as general maintenance rules, which cannot integrate the particular data from each installation. Therefore, it is subjected to modifications whenever required.



BEHAVIOUR UNDER HEAVY ROLLING LOAD (CHERRY PICKER, FORKLIFT.....)

■ Before positioning of this kind of device on the covering you should protect the sport flooring –on all the rolling area - by using a double coat of 19mm plywood, these planks should be stacked but the junctions should not. This method tends to lower the pressure on the floor (weight distribution), and prevent the covering from being punched.



CAUTION, DO NOT USE:

- Benzine, toluol, acétone, tétrachlororoethene, thinner, oilwax or strong scouring powders......
- Black rubber tires (pad on the feet of seats, bench....) can cause permanent discolouration and should not be used.
- If unsure, protect the floor by placing a piece of carpet, cardboard or similar material underneath.

The information given in this technical specification is indicative. It is based on our knowledge and experience. It has to be considered as general maintenance rules, which cannot integrate the particular data from each installation. Therefore, it is subjected to modifications whenever required.

